

WAX CANDLE




Production capacity/annum

150 M.T.

Production process

- Setting up of machine
- Loading of Bobbins
- Threading of Machine
- Adjustment of Candle Lengths
- Pouring of Wax
- Cooling
- Ejection of Candles
- Removal of Candles.

Process flow chart



Machinery & equipment required

- Semi Automatic Candle making machine : 4 Nos.
- Hot Plate : 2 Nos.
- Melting Pan : 3 Nos.

Raw material/consumables required

- Paraffin.
- Thread.
- Castor Oil/Coconut Oil.
- Packing Material.

Utilities required

Power required (load) : Normal single Phase Supply
Water required (per shift basis) : Normal Supply.

Manpower required

- Supervisor : 1 No.
- Skilled Workers : 2 Nos.
- Unskilled Workers : 4 Nos.

Area required

Total Area : 200 Sq.Mtr.
Covered Area : 150 Sq.Mtr.

Investment required

Machinery & Equipment : } ₹ 28.5 Lakhs
Working Capital for 3 Months : }
(Raw material, utilities & salary)

